

2014-04-23	<p>Bug fixed</p> <ul style="list-style-type: none"> - Fixed DNS error when using it with DHCP at the TCP Client Mode - Fixed DHCP parser error when processing DHCP option field 0. - Fixed the error that "Ethernet to UART" function operates when the remote IP information is not correct at the UDP mode <p><u>WIZ107SR(HW Ver. 1.3 / 1,4) Firmware</u></p>	4.03
2013-11-07	<p>Bug fixed.</p> <ul style="list-style-type: none"> - PHY Initialization Check routine was revised - Problem about handling serial command mode was fixed => WIZ107SR jumps to serial command mode when it received data having serial command triggering character set from its serial was fixed. <p><u>WIZ107SR(HW Ver. 1.3) Firmware</u></p>	3.14
2013-06-10	<p>Bug fixed.</p> <p>WIZ107SR can be used the serial command mode without connecting LAN cable.</p> <p><u>WIZ107SR(HW Ver. 1.3) Firmware</u></p>	3.11
2013-02-22	<p>Problem fixed.</p> <p>WIZ107SR sends DHCP Request Packet after DHCP lease time.</p> <p><u>WIZ107SR(HW Ver. 1.3) Firmware</u></p>	3.10
2013-02-08	<p>Modified serial command mechanism in order to use stable operation.</p> <p>Added function for sending DHCP Request Packet when reconnect LAN cable.</p> <p><u>WIZ107SR(HW Ver. 1.3) Firmware</u></p>	3.07
2012-11-15	<p>Release</p> <p><u>WIZ107SR(HW Ver. 1.3) Firmware</u></p>	3.04
2013-02-22	<p>Problem fixed.</p> <p>WIZ107SR sends DHCP Request Packet after DHCP lease time.</p> <p><u>WIZ107SR(Old HW Ver. 1.1) Firmware</u></p>	2.20
2013-02-08	<p>Modified serial command mechanism in order to use stable operation.</p> <p>Added function for sending DHCP Request Packet when reconnect LAN cable.</p> <p><u>WIZ107SR(Old HW Ver. 1.1) Firmware</u></p>	2.17